


# PIKE RIVER MINE DISASTER

What went wrong

**STEWART BELL**

**CIC FAIOH MRACI CChem PSM**

**Commissioner for Mine Safety and Health**



# Pike River

- 19<sup>th</sup> November 2010 - 31 men went to work at the Pike River Mine and 29 never returned home
- The Royal Commission was established in late December 2010
- The Commission was chaired by Justice Graham Panckhurst, with David Henry and the author as the other Commissioners
- The final report was presented to the Governor General of New Zealand on the 30<sup>th</sup> October 2012
- The lessons from Pike River must be remembered




# Pike River Mine

Atarau, Greymouth, New Zealand




Daniel (Dan) Herk  
36, Runanga



David (Dave) Hoggart  
33, Greymouth



Richard (Rolls) Holling  
41, Blackball




Koos Jonker  
47, Limpopo, South Africa



Peter (Pete) Rodger  
40, Perth, Scotland



Blair Sims  
28, Greymouth



Keith Valli  
62, Nightcaps



Terry Kitchin  
41, Runanga



Joshua (Josh) Ufer  
25, Charters Towers, QLD, Australia




Zen Drew (Verhoeven)  
21, Greymouth



Kane Nieper  
33, Greymouth



Riki (Rik) Keane  
28, Greymouth



Conrad Adams  
43, Greymouth



Malcolm Campbell  
25, St. Andrews, Scotland



Glenn Cruse  
35, Greymouth



Allan Dixon  
59, Runanga



Christopher (Chris) Duggan  
31, Dunollie



William (Wille) Joynson  
49, Maryborough, QLD, Australia



Stuart (Stu) Mudge  
31, Runanga



Peter O'Neill  
55, Runanga



Brendon Palmer  
27, Greymouth



Samuel (Sam) Mackie  
26, Christchurch




Milton (Milt) Osborne  
54, Ngahere



Joseph Dunbar  
17, Christchurch



Benjamin (Ben) Rockhouse  
21, Singleton, NSW, Australia



Michael Monk  
23, Greymouth



John Hale  
45, Hokitika




Andrew (Huck) Hurren  
32, Hokitika



Francis Marden  
41, Barrytown



Pike River Coal



Subtech Services



VLI Drilling




Boyd Kilkelly Builder



Graeme Pizzato Contracting



CYB Construction







PIKE RIVER COAL

# UNDERGROUND TAG BOARD

## IN



PIKE RIVER COAL

ALL CONTRACTORS & VISITORS  
MUST SIGN IN WITH THE  
CONTROL ROOM OFFICER  
BEFORE GOING UNDERGROUND

Please make  
sure you  
have removed  
your tag  
from the  
board

Work Safe

Play Safe

Home Safe

# Pike River

The first explosion occurred at around 3.45 pm on the 19<sup>th</sup> November

The second explosion 24<sup>th</sup> November 2.37pm

The third explosion 26<sup>th</sup> November 3.39pm

The fourth explosion 28<sup>th</sup> November 1.50pm

Re-entry into the mine has not been achieved to date







Figure 8.10: The surface fan after the first explosion











# Rugged Terrain



**Pike River Coal – New Zealand's Only Listed Local Coal Mining Company**






PIKE RIVER  
COAL LTD.

Mine Workings, Topography  
Resouce 101119\_181

DATE: 10/01/2011  
DRAWN BY: G. Hume  
PROJECT: 101119\_181  
SCALE: 1:2000



# Pike River Mine Plan



Development areas

Goaf

Sandstone zone (graben)

Hydro panel

Hawera Fault

Three main roadways

Vent shaft

Fan



Pit bottom in stone

Access drift (2.3 km to portal)

Spaghetti Junction

Slimline shaft and fresh air base (FAB)

Pit bottom south



# Brunner Seam properties

- Depth of cover –110 to 180m
- High quality coking coal (very low ash & sulphur)
- 8 -9m thick (average)
- Gradient variable ( 5 –15)
- Spontaneous combustion propensity (Moderate)
- Gas content –approx 4 –9 m<sup>3</sup>/t (methane)





















# Gas monitoring



# Monitoring











Loading GAG unit and equipment onto NZ Hercules and final space



# Górnicy Agregat Gaśniczy (GAG)







# Pike River – QMRS Logistical Operations

- 160,000 m<sup>3</sup> mine volume
- 71 days involvement
- 39 days of Jet Operation
- 706 hours of product delivery
- 63,212,000 m<sup>3</sup> of product
- 25,416,000 m<sup>3</sup> of inert gas
- 1,504 litres per hour - fuel
- 1,061,869.89 litres of fuel
- Fuel cost \$700,834 NZ
- 649 shifts over 71 days
- 7,788 hours
- 1,134 person nights accommodation.
- 246 people movements (flights)
- 36 people involvement
- Air Travel - \$96,063
- Accom. - \$101,591
- Transport/meals/misc – \$129,383







# First Steps Back In





# What happened at Pike River

- Methane explosion. Significant volume of gas involved possibly related to the hydro panel goaf collapsing. Weak explosion inbye the main fan.
- This would have resulted in an oxygen deficient atmosphere with high CO levels. Anyone who didn't escape from the mine in the first 1-2 hours was not going to survive
- Source of ignition not clear but most likely electrical possibly linked to the earthing system and VSD induced harmonics
- Other possibilities included contraband, diesels and frictional ignition

# What Happened

- If entry to the mine stone drive is achieved this could be clarified by examining the VSDs
- No-one survived the initial blast other than the two miners who escaped
- Sealing the mine would possibly have avoided the final three explosions
- There was no clear window of opportunity to re-enter the [mine](#)



# What went wrong


- Pike was a problem mine from the start, constant changes to the mine plan
- 7 mine managers in 2 years
- Lack of consistent leadership
- Difficult topography, mountainous terrain, high rainfall
- Bad geology- faults and grabens, poor delineation of the coal seam
- Gas issues- high methane content coal
- Hydromining commenced too early before the ventilation was stabilised.
- Pike needed the best of everything

# What went wrong

- The commission identified a range of issues
- Production versus safety. The mine was always under financial stress
- Methane drainage issues- free venting of methane into the return
- Expert consultants engaged but advice often not taken, ventilation, methane drainage and hydromining
- Unique electrics- high usage of VSD's- issues with restricted zones
- Lack of worker involvement in safety
- SHMS not fully developed
- Risk assessment processes were flawed



NO EFFECTIVE  
SECOND MEANS  
OF EGRESS





**FRESH AIR BASE**









# UNDERGROUND MAIN FAN

- VENTILATION  
SHORTFALL
- POORLY BUILT  
STOPPINGS



# Pike River Mine Plan







# What went wrong


- Lack of experienced miners- not enough mentors
- contraband issues
- Poor contractor control. Poor training
- Lack of an effective regulator. Only 2 mines inspectors
- Problems with the rescue and recovery effort- non mining incident controller
- Next of kin issues
- Ineffective corporate governance

# COMPROMISED GAS MONITORING SYSTEM

NO OPERATIONAL  
GAS MONITORS IN  
THE MAIN RETURN



# Pike River Mine Plan



# What the gas monitoring should have been




Figure 10.2: Plan of required gas sensors at Pike River under Queensland legislation<sup>27</sup>

# Monitoring system failure was evident

## Problems with the sensors in the ventilation shaft

19. There were several problems with the gas sensors in the ventilation shaft. First, the sensor at the bottom of the ventilation shaft stopped working on 4 September 2010, nearly 11 weeks before the explosion, and was never repaired or replaced.<sup>31</sup> Indeed, the control room operator's screen on the Safegas system was permanently annotated to say the sensor was 'faulty' and 'waiting for spare'.




Figure 10.4: Control room operator's screen on the Safegas system<sup>32</sup>



# POORLY INSTALLED SYSTEMS




# OVERALL

IN EVERY AREA WE  
LOOKED AT, THERE  
WERE PROBLEMS



# Swiss Cheese Model



# Applicability to Australia

- Qld and NSW Inspectorates are jointly examining size requirements for explosion panels in mine fans.
- Variable speed drives need to be assessed?
- Ensure risk assessments are done properly and that the controls are the focus
- Training of mine workers re self escape
- Role of the Board

# Applicability continued

- Don't short circuit incident investigations
- Cultural issues such as dealing with families after events such as Pike need to be addressed
- Inexperienced mine workers
- The rescuer model
- Leadership failed
- **Don't think this can't happen here**



# In conclusion

- We don't have any choice here
- Australia and New Zealand must learn from this disaster
- 29 of our colleagues paid the ultimate price



**Every miner home safe  
and healthy every day**



# Decisions – in a nutshell



**Decisions can be life taking  
Decisions can be life giving  
Its your call...**