

ACARP Project C23005

Use of plastic metal for temporary repair
of flamepath on flameproof equipment
used in underground coal mines

Background

- When certified flameproof equipment is inspected and a defect is identified such as corrosion of flamepath or deformation due to trapped cable or washer or a debris. The equipment will need to be repaired.
- In-situ method would be to repair by welding
- This process has risks – hot surface, arcs and sparks
- Can it be repaired temporarily without welding?

Poor or no maintenance ?



Consequence



Objectives of the study

- To determine if it is feasible to use plastic metal for temporary repair of flamepath
- Determine limitations of application and use
- Conduct tests beyond those specified in the protection standards
- Inform industry and regulators of findings
- Establish test criteria for plastic metals
- Establish competency for person undertaking repair

Selection of products

- There are a number of products available that may be suitable for temporary repair of flamepaths




Analysis

- Type of compound
 - liquids (2 part, epoxy plus powder),
 - Putty
- Continuous Operating Temperature (COT) range
- Curing time
- Shelf life
- Compound Property
 - Tensile strength
 - Thermal conductivity
 - Hardness



Selection of suitable enclosure

- Ideal – Obtain existing certified enclosure
- Next Best - fabricate




Selection of suitable enclosure

- Prepare slots for material testing
- 10mm, 8mm, 6mm (Square), 4mm & 2mm (V-slot)



Prepare material

- Each compound was prepared as per manufacturers specification





Prepare material

- Each compound was prepared and finished such that the surface finish was around $6.3\mu\text{m}$



Testing of enclosure

- Testing of fabricated enclosure to prove compliance with IEC 60079-0 & IEC 60079-1 (Reference pressure determination tests)




Testing of enclosure


- Testing of fabricated enclosure to prove compliance with IEC 60079-0 & IEC 60079-1 (Hydrostatic overpressure test)



Material Preparation




Material Preparation




Conditioning of material

- Thermal endurance test
 - 4 weeks at 95°C and 90% RH
 - 24 hours at ambient temperature of 25°C
 - 24 hours at -25°C



Testing and observations

- Impact tests on the potting in through holes
- Reference pressure determination tests with the compound (potting)
- Hydrostatic test at 1060 kPa applied for 60 s
- Flame non-transmission tests



Testing and observations

- Flame non-transmission tests
 - 5 test conducted using hydrogen methane mix
 - No transmission, however minor erosion of material



Testing and observations


- Flame erosion tests
 - 50 tests conducted using 9.8% methane in air mix



- No transmission

Testing and observations

- Flame erosion tests
 - Closer inspection



Testing and observations

- Other compounds



Next Steps

- Conduct further tests of flamepath that are damaged due to the following:
 - Trapped washer in flange of flameproof enclosure
 - Impact damage on flamepaths (roughly in the middle of flamepath)
 - Test for various sizes and depth
 - Obtain feedback from end users (mines), inspectorate and the OEMs
 - Prepare plastic metal material testing criteria
 - Prepare competency requirements for undertaking repair

Indentations




Washer imprint across
the flamepath


Impact damage across
the flamepath

Deep stretch across
the flamepath

New thin cover plate




Front view of 8 mm thick plate



Back view with indentations

Flamepath damaged by corrosion



Flamepath etched with acid
on 8 mm thick cover plate



Flamepath etched with acid on
thick cover plate

Conclusions

- Stage 1 – Feasibility study indicated that it is possible to repair flamepaths by use of certain plastic metal
- Test criteria is almost established and will be completed at end of Stage 2
- Original Equipment Manufacturer (OEM) must accept before proceeding with temporary repair
- Include in AS/NZS 2290.1 for temporary repair

Interim ACARP Report

- For details, interim ACARP report is available from ACARP project C23005
- <http://www.acarp.com.au/report>

Any questions?

